

FIG. 1




FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2





FIG. 24






FIG. 20




FIG. 2E




FIG. 2F




FIG. 2G




FIG. 2H




FIG. 2I




FIG. 2J




FIG. 2K




FIG. 3





FIG. 3A

FIG. 4






FIG. 5

—PROGRAMMING————MONITOR INFORMATION————CONTROL INFORMATION




FIG. 6A




FIG. 6B




FIG. 7

PROGRAMMING  
SWITCH CONTROL INSTRUCTIONS




FIG. 7A




FIG. 7B

PROGRAM

- - - CONTROL INFORMATION

+++ MONITOR INFORMATION




FIG. 7C




FIG. 7D




FIG. 7E




FIG. 7F

# PROGRAMMING CONTROL INFORMATION




FIG. 8